Site	Description	Actions
Aintree Road	Highway Flooding	Investigated and cleaned – Due to volume of water received
Waverly Close	Highway Flooding	Investigated and cleaned – Due to volume of water received
Seaton Road	Highway Flooding	Investigated and cleaned – Due to volume of water received
Taverners Road	Highway Flooding	Investigated and cleaned – Due to volume of water received
Brenchley Close	Highway and Garden Flooding	Investigated and cleaned – Due to volume of water received
Thompson Close	Highway Flooding	Investigated and cleaned – Due to volume of water received
Wilson and Haig Avenue	Highway and Internal Flooding	Investigated, Cleaned and Council have undertaken formal investigation
Bond Road	Internal Flooding	Council undertaking feasibility as previously flooded
Pine Grove	Internal Flooding	Investigated and cleaned – Due to volume of water received
Deanwood Drive/ Lovelace Close	Highway Flooding Lifted Manholes	Investigated and cleaned – Due to volume of water received
Bredhurst Road, Gillingham	Highway Flooding Lifted Manholes	Investigated and cleaned – Due to volume of water received
Maidstone Road/ Asquith Road	Highway Flooding Lifted Manholes	Investigated and cleaned – Due to volume of water received
Scotby Avenue	Highway Flooding	Investigated and cleaned – Due to volume of water received
Findley Close	Internal Flooding	To be investigated
Campleshon Road	Highway Flooding	Investigated and cleaned – Due to volume of water received
Tadwell Road	Highway and Internal Flooding	Investigated and cleaned – Due to volume of water received
Parker Close	Highway Flooding	Investigated and cleaned – Due to volume of water received
Cherry Tree Road	Highway and Internal Flooding	Investigated, cleaned and Council will undertake formal investigation
Walderslade Road	Highway Flooding	Investigated and cleaned – Due to volume of water received
Wheatcroft Grove	Internal Flooding	To be investigated
Taswell Close	Highway Flooding	Investigated and cleaned – Due to volume of water received
Solomon Road	Highway and Internal Flooding	Investigated and cleaned – Due to volume of water received
Prince Charles Avenue	Highway Flooding	Investigated and cleaned – Due to volume of water received
Street End Way, Brambledown	Highway Flooding	Investigated and cleaned – Due to volume of water received
Barrington Close	Highway Flooding	Investigated and cleaned – Due to volume of water received
Churchill Avenue	Highway Flooding	Investigated and cleaned – Due to volume of water received
Nelson Terrace	Internal Flooding	Council undertaking feasibility as previously flooded
Scott Avenue	Highway Flooding	Investigated and cleaned – Due to volume of water received
Mierscourt Road	Highway and Internal Flooding	Investigated and cleaned – Due to volume of water received
Silver Spot Close	Highway and Internal Flooding	Investigated and cleaned – Due to volume of water received
Harvester Close	Highway and Internal Flooding	Investigated and cleaned – Due to volume of water received